# **EXHIBIT DD**

#### ETHICO N, INC.

a Johnson Johnson company
P.O. BOX 151
SOMERVILLE • NEW JERSEY • 06878-0151

August 10, 1990

Ms. Karen Braun

cc: Dr. J. Lefelar

Dr. J. McVey

Dr. A. Melveger

Dr. B. Schwartz

TEN YEAR *IN VIVO* SUTURE STUDY SCANNING ELECTRON MICROSCOPY FIVE YEAR REPORT

#### Introduction

Twenty-four Beagle dogs had been implanted in November 1985 with sets of ETHILON™, PVDF, PROLENE™ and Novafil 5-0 sutures subcutaneously in the fascia of the lateral dorsal thorax. Five years later, in June and July of 1990, five dogs were euthanatized and the suture implants removed. The explants were received in the microscopy department in weekly intervals.

#### **Experimental**

One set of sutures from 5 dogs (#1994, 2000, 2006, 2012, 2018), six sites per dog, was received in sterile water in plastic vials. In some cases a short length of the suture was above the water surface and this segment was discarded. The wet total length of each of the sutures was placed on a micro slide with water from the vial to keep the suture wet. The sample was covered with a cover slip and then examined in the Zeiss compound optical microscope at 110x magnification under crossed polars. Photomicrographs of areas of interest however, were not prepared under crossed polars but in ordinary transmitted light. Current instrumentation does not provide for low light level photomicroscopy, which meant a loss of some of the observations made under crossed polars. (SEM photomicrographs were used instead to show these findings.)

Segments of the wet sutures which showed areas of interest were then air dried overnight and divided in half. One half was examined in its dry state under crossed polars in the Zeiss light microscope. Photomicrographs were prepared in ordinary transmitted light at 110x magnification. The other half was mounted on a carbon stub with copper tape and sputter-coated with gold under vacuum to provide an electron conductive surface. These suture segments were then examined in the JEOL JSM 840 AII SEM. Photomicrographs were prepared at 500x magnification.

Page 2

#### Results and Discussion

Results of light microscopy in the wet and dry state will not be discussed here in detail. A table is included in this report which summarizes the light microscopical (LM) observations. It can be said unequivocally that the cracking that was seen in any of the sutures was not introduced by sample preparation, i.e., drying. If cracking was observed on a dry suture in the light microscope or in the SEM, the same cracking was also found on the same suture after it had been in body fluids and then in sterile water, without ever having dried.

SEM of ETHILON Explants: Figure 1, 2

Suture explants from all five dogs from all sites showed cracking and abrasions in at least 30% of the total suture surface. The abrasions were deep enough to loosen the dyed surface layer of several microns. The cracking shown was found in the undyed underlying layer.

SEM of PVDF Explants: Figure 3, 4

No cracking or abrasions were found in any of the explants. A few longitudinal score marks and some mechanical damage, probably not due to degradation, were observed.

SEM of PROLENE Explants: Figure 5, 6

Explanted sutures from dogs 1994, 2000 and 2006 did not show any cracking or abrasions. On explants from dogs 2012 and 2018 a few cracked areas were observed; both of these sutures came from site 4.

SEM of Novafil Explants: Figure 7, 8, 9

None of the transverse cracking as seen in PROLENE and ETHILON was found on these sutures. Longitudinal cracks with suture material peeling away from it were found on most of the explants. Mechanical damage, probably not due to degradation, was also observed in one case. However, when the oldest explant was reexamined after it had been in sterile water for 45 days, small transverse cracks were found in one area.

#### Conclusions

After 5 years *in vivo* the PVDF 5-0 suture was the only explanted material from five dogs which did not show any surface damage due to degradation. Out of seven PROLENE explants, two revealed cracking. All ETHILON explants were heavily cracked and abraded down to the undyed underlying layer. The Novafil explants exhibited longitudinal cracks and in one 45 day old explanted suture some transverse cracking was observed.

Page 3

These results may be compared with those of the two year study. (Memo by Frank Schiller 8-26-87.) ETHILON had shown cracking at the two year point; at five years the cracked surface was abraded down to the underlying undyed layer. The PROLENE surface, intact at the two year point, showed signs of degradation at five years. The only intact surface after five years was that of all the PVDF explants. Novafil results seemed to be more ambiguous.

E. Lindemann


Elle Gunclem ann


DOG.EL Attachment LM Observations on Explanted Sutures after 5 Years in Dogs

	In Observations on Explanted Sutures after 5 years in Dogs						
SR #	Suture	Dog	Site	LM H <sub>2</sub> O	LM dry	Photo #	
30691	PROLENE	1994	1	No Damage	No Damage	Damage 2280, 2336	
	PVDF		2	No Damage	No Damage	2281, 2337	
	ETHILON		3	Damage	Damage	2282, 2338	
	Novafil		4	No Damage	No Damage	2283, 2339	
	PROLENE		5	No Damage	Damage	2284, 2340	
	ETHILON		6	Damage	Damage	2285, 2341	
30702	Novafil	2000	1	No Damage	No Damage	2286, 2300	
	PROLENE		2	No Damage	No Damage	2287, 2301	
	PVDF		3	No Damage	No Damage	2288, 2302	
	ETHILON		4	Damage	Damage	2289, 2303	
	Novafil		5	No Damage	No Damage	2290, 2304	
	PROLENE		6	No Damage	No Damage	2291, 2305	
30716	ETHILON	2006	1	Damage	Damage	2294, 2306	
	PVDF		2	No Damage	No Damage	2295, 2307	
	PROLENE		3	No Damage	No Damage	2296, 2308	
	Novafil		4	No Damage	No Damage	2297, 2309	
	PVDF		5	No Damage	No Damage	2298, 2310	
	Novafil		6	No Damage	No Damage	2299, 2311	
30725	PVDF	2012	1	No Damage	No Damage 2312, 2	2312, 2318	
	ETHILON		2	Damage	Damage	2313, 2319	
	Novafil		3	No Damage	No Damage	2314, 2320	
	PROLENE		4	Cracking	Cracking	2315, 2321	
	ETHILON		5	Damage	Damage	2316, 2322	
	PVDF		6	No Damage	No Damage	2317, 2323	
30785	ETHILON	2018	1	Damage	Damage	2324, 2330	
	Novafil		2	No Damage	No Damage	2325, 2331	
	ETHILON		3	Damage	Damage	2326, 2332	
	PROLENE		4	Cracking	Cracking	3227, 2333	
	PVDF		5	No Damage	No Damage	2328, 2334	
DOG FL /2	Novafil		6	No Damage	No Damage	2329, 2335	

DOG.EL/2


### Ethilon Explants





Dog #1994 Site 3


Dog #1994 Site 6




Dog #2000 Site 4

Dog #2006 Site 1

### Ethilon Explants









Dog #2012 Site 2


Dog #2012 Site 5






Dog #2018 Site 1


Dog #2018 Site 3





**BADE** Explants


Dog #2018 Site 5




Dog #2012 Site 6

TOM

Dog #2012 Site 1







PVDF Explants

Dog #2000 Site 6


Dog #2000 Site 2






Dog #1994 Site 5


r 91i2 46er# god






Prolene Explants

Pog #2018 Site 4





Dog #2012 Site 4

Dog #2006 Site 3




Prolene Explants






Novafil Explants



Novafil Explants

Movafil Explant

45 Days After Explantation



4 91i2 499f # god

Case 2:12-md-02327 Document 3652-30 Filed 04/13/17 Page 15 of 15 PageID #: 128617

0933

#### ETHICO N.INC.

## 30785

**ANALYTICAL CHEMISTRY DEPARTMENT** 

64506			
· 多种种的 (1968年) · 中华发生 (1968年) · 1980年			
Karen Braun ERF 2996 7-9-	90 161	02 John Defending	-7/9/90
SAMPLE IDENTIFICATION SPECIAL STORAGE CONDITIONS. PRECAUTIONS  85-219 DOG # 2018:  Site 1-ETHILON 4-PROLENE  2-Novafil 5-DINE	ure was show any plants 2 ted and afil	THE ONLY EXPLANTS  NO. SAME  THE ONLY EXPLANTS  NO. SAME  THE ONLY EXPLANTS  NO. SAME  THE ONLY EXPLANTS  THE ONLY EXPLANTS  NO. SAME  THE ONLY EXPLANTS  THE ONLY EX	ETO MONO COMP
		la la la la U W	5
		JUL   0 199	
		OR AU MELVEC	SER .
CONCLUSIONS/COMMENTS:			io in Y
CONCLUSIONS/COMMENTS:		REF. 2334-22-	-23
01/			
ANALYST BURNISOR OF A DATE ANALYST ANA	DATE	SECTION MANAGER	DATE
ANALYST/SUPERVISOR  DATE ANALYST/SUPERVISOR  FALTE/BRY A/BS	DATE	DEPT. MANAGER	DATE

ANALYTICAL CHEMISTRY DEPT. COPY